

# Contents

Safety1
Package Contents1
Unpacking1
Installation2
1. Environment Required2
2. Install Spectrophotometer2
Overview
Symbols
Main Specifications
Description of Appearance and Keys4
1. Appearance4
2. Keypad
3. Description of Keys5
Functions6
Getting Started6
Important Guidelines7
General Operating
Measuring9
1. Photometry9
2. Quantitation10
3. Kinetics
4. Utility
Turn On/Off D2 Lamp16
Turn On/Off W Lamp16
Set Date & Time17
Get Dark Current17
Reset Wavelength17
Lamp Life

Load Default Parameters	
Lamp Change	
About Version	19
Troubleshooting	19
Repair and Maintenance	20
1. Daily Maintain	20
2. Spare Parts Replacement	20
Warranty	25
Equipment Disposal	26

# Safety

Please follow the guidelines below, and read this manual in its entirety to ensure safe operation of the unit.

We recommends against the use of SCI-UV1100 Spectrophotometer.



- Do not open the device.
- Disconnect the device from the mains supply before carrying out maintenance work or changing the fuses.
- The inside of the device is a high-voltage area Danger!
- Do not use the device if it is damaged, especially if the main power cable is in any way damaged or defective.
- Repairs may only be carried out by the service technicians from us and authorized contractual partners.
- The device must be connected to a power outlet that has a protective ground connection.
- If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.



- Do not allow any liquid to enter into the device.
- Do not operate the device in a hazardous location or potentially explosive environment.

## Package Contents

Description	Quantity
Spectrophotometer	1PC
10mm Glass Cuvette	4PCS
10mm QuartzCuvette	2PCS
Power Cord	1PC
User's Manual	1PC
Dust Cover	1PC

# Unpacking

Open the package, according to carefully check the packaging packing list items, if found inside the packaging are missing or damaged items please

contactus and authorized contractual partners.

### Installation

### 1. Environment Required

To ensure the best performance, the following conditions are required:

- The best working temperature range is 16-35 C and the humidity is 45-80%.
- Keep it as far as possible away from the strong magnetic or electrical fields or any electrical device that may generate high-frequency fields.
- Set the unit up in an area that is free of dust, corrosive gases and strong vibrations.
- Remove any obstructions or materials that could hinder the flow of air under and around the instrument.
- The power requirement is  $110\pm11V/60\pm1Hz$  or  $220\pm22V/50\pm1Hz$ .
- Use the appropriate power cord and plug into a grounded outlet.
- If the local voltage is not stable, a voltage regulator is required.
- Be away from direct sunlight.

### 2. Install Spectrophotometer

#### Placement

Place the instrument on the stable table carefully.

#### Install Printer (Printer is Optional Accessories)

Check to confirm instrument power switch is turned off, connectthe printer's data cable to the instrument's parallel port.

#### Link the Power Cord

Check to confirm instrument power switch is turned off, the power cord plug into two separate power interface and power supply socket apparatus.


### Overview

SCI-UV1100 Spectrophotometer is an electrical measure instrument which is widely used in the laboratories.

•	Use Frequency:	Intermittence
•	Excessive Voltage(Current):	No
•	Pollution Class:	Class 1

# Symbols

The following chart is an illustrated glossary of the symbols that are used in this manual.





Recycle, this instrument will be called back by the appointed Electrical Treatment Department or by the original Manufacturer when wasted.

# Main Specifications


•	Optical System	Single beam
•	Wavelength Range	190—1100nm
•	Wavelength Accuracy	±0.5nm
•	Wavelength Repeatability	0.3nm
•	Photometric Range	-0.3-3A, 0-200%T
•	Photometric Accuracy	±0.5%T
•	Photometric Repeatability	0.3%T
•	Spectral Bandwidth	2nm
•	Stray Light	0.05%T@220nm&360nm
•	Stability	±0.002A/h@500nm
•	Work Mode	Photometry, Quantitation, Kinetics
•	Interface	USB, Parallel(printer)
•	Power Requirement	AC 110/220V, 50/60Hz

•	Dimensions	490x360x240
•	Weight	14kg
•	Work Environment	15 $-35$ °C,15 $-70$ % relative humidity
•	StoreEnvironment	-10–50 $^\circ C$ , 15–70% relative humidity

# Description of Appearance and Keys

### 1. Appearance

Front View



Back View




- 1 LCD Display
- 2 Keypad
- 3 Lid of Sample Room
- 4 Rod
- 5 LCD Contrast Adjust

6 Printer port

- 7 USB port
- 8 Cover of Fan
- 9 Power Socket
- 10 Power Switch


11 Cover of Cooling Vents

### 2.Keypad



# 3. Description of Keys

S E T	SET Key: Set Parameters
G O T O <b>A</b>	GOTO & Key: Set Wavelength
ZERO	ZERO Key: Blank



### Functions

Photometry
Display results as Abs, %T or Energy.

#### Quantitation

We provide 2 methods to establish a Standard Curve:

- Up to 9Standard Samples to establish Standard Curve;
- Input coefficients to establish Standard Curve.

#### Kinetics

- Record up to 1000 points;
- 2 Photometric Mode to display the curve (%T-Time & Abs-Time).

## Getting Started

The following chart describes the basic operation of the instrument.

#### Turn On and Self-check

Switch on the power. Then the instrument begins to self-check and 20 minutes' warm up. Self-check includes the following steps:Turn on lamps  $\rightarrow$ Check Sensor  $\rightarrow$  Initialize AD  $\rightarrow$  System position  $\rightarrow$  Get Dark Current  $\rightarrow$  Warm up.

√Self-testing
● Filter
O W Lamp
O D2 Lamp

Warm up 20 minutes, "ENTER" to skip

After warm up, instrument displays Main Interface.

● Photometry	
O Quantitation	
O Kinetics	01/01
O Utility	01/01 00:00

### Important Guidelines

- Reagents and dilution buffers can cause cauterization and other damage to health.
- Samples (nucleic acids, proteins, bacteria cultures) can be infectious and cause serious damage to health.
- During sample preparation, measuring procedures and maintenance and cleaning work, observe all local laboratory safety precautions (e.g. wear protective clothing and gloves, use of disinfectant) regarding the handling of sample material.
- Dispose of measuring solutions and cleaning and disinfectant materials in accordance with the relevant local laboratory regulations.

# General Operating

#### Select Application

Main Interface, press numeric key or , to choose corresponding menu,

		ENTER	
then	press		•

#### Set Wavelength

GOTO **K** to set wavelength, input the values by pressing Numeric keys, Press ENTER togo to the point you set, thendo blank automatically. press

Photome	etry		
WL=546.	0nm		
Please	enter	WL	
WL=			

#### Set Parameters

In different applicat	ion, press SET to set p	arameters, press
to choose or input the	values by numeric keys, pre	ess ENTER to enter into,
press RETURN to return	rn.	

#### Set Auto-cell Holder (optional)

Press the numeric key (1-8) to make corresponding cell position at the light path.

#### Delete the Input Value

 $\square$ 

	CLEAR					
Press		to	delete	all	the	characters

#### Delete the test results and stored data



CLEAR ) to delete the test result or stored data.

#### Blank

Put	the	Reference	in	the	light	path,	press	ZERO	to	do	blank.

#### Measure Samples

Put the samples in the light path, press  $\frac{START}{STOP}$  to measure.

#### Print the test results

 $\overline{PR \mathbb{N}T}$  to print the test results. Press

#### Load the Standard Curve



# Measuring


### 1. Photometry

Step 1. StartPhotomet	ry	
MainInterface, press n	umericke	y ar , to choose "Photometry",
then press ENTER.		
Photometry		Photometry
O Quantitation		
O Kinetics	01/01	0. 032A
O Utility	00:00	500. Onm
Step 2. Set Photometr:	ic Mode	
Press SET to set p	hotometr	ic mode. Press, Vto choose "Abs.",
"T%" or "Energy".And p		TER to confirm.Press RETURN toreturn.
Photometry		√Photometry
0.032A 500.0nm		<ul> <li>O Abs √</li> <li>O %T</li> <li>O Energy</li> </ul>
l		

#### Step 3. Set Wavelength

Press $\begin{bmatrix} G \ 0 \ TO \ \textbf{\textit{k}} \end{bmatrix}$ to set wavelength, key in the wavelength by using Numeric	Press
ceys, press Enter.	keys,

#### Step 4. Enterinto MeasuringInterface



#### Step 5. Blank

Put the Reference in the light path and press \_\_\_\_\_\_to do blank.


#### Step 6. Measuresamples

Put the sample in the light path, and then the result displays on the

screen automatically, press  $\frac{START}{STOP}$  to record.


500.	Onm	0.041A
No.	WL	Abs
1	500.0	0.039
2	500.0	0.042
3	500.0	0.041


### 2. Quantitation



#### Step 2. Establishor call Standard Curve

2 methods to establish Standard Curve:






7) Calibrate Standard Samples.Put the corresponding standard samples in the light path as the screen indicates, input the concentration

of the corresponding nd press

ENTER to measure.



Method 2: Establish Standard Curve by inputting coefficients


1) Starts establish.Press , to select "Coefficient", select C=KxA+B, then press ENTER to confirm.
✓Quantitation


Standard Curve
Coefficient
Coefficient

0.000Abs

0.000Mp/ml
500.0nm


2) Enter into Set Interface.Press





#### Step 3. Enterinto MeasuringInterface

Press START to enter into the QuantitationMeasuringInterface.



#### Step 4. Blank

Put the Reference in the light path, press to do blank.


#### Step 5. Measure Samples

Put the sample to be tested in the light path, press Then the test result will display in the data sheet. Repeat this step to finish measuring all the samples.

500	.Onm	0	.000A
No.		Abs	mg/ml
1	500.0	0.039	0.078
2	500.0	0.042	0.084
3	500.0	0.041	0.082

### 3.Kinetics


Step 1.	Start Kinetics					
Main	Interface, press	3 or △, ▽ to	select	"Kinetics"	and	press
ENTE	to confirm.					




#### Step 2. Set Wavelength


Press	GOTO K	to	set wavelength,	inputwavelength	by	Numeric	keys,	and
press	EN TER	to	confirm.					

#### Step 3. Setup Parameters





Step	4.	Enter	into	Mea	suring	gInt	erface
Pr	ess	START STOP	to e	nter	into	the	KineticsMeasuringInterface.



#### Step 5. Blank


Put the Reference	in	the	light	path,	press	ZERO	to	do	blank.
-------------------	----	-----	-------	-------	-------	------	----	----	--------

#### Step 6. Measure Samples


START Put the sample in the light path and press to begin, repress RETURN it to stop, and press to cancel.


120.0			
0			
	0s		100s
500. Or	nm	27s	100.0%T

### 4. Utility




**O** W Lamp 0n O Date&Time






"Reset WL", then press to reset wavelength.




#### Lamp Life

Press, to choose "Lamp Life", then press to enter into. Select "Display Lamp Life" to view the W Lamp and D2 Lamp has been used time. Select "Reset D2 Life" or "Reset W Life" to reset the time.




#### Load Default Parameters

Press, to choose "Load Default", then press Inter to enter into. Select "Yes" to load the parameters to factory setting and the instrument will restart.



# Lamp Change Press, to choose "Lamp Change", then press ENTER to enter into. Input switch wavelength (325-375nm)and press ENTER to confirm.



# Troubleshooting

Review the information in the table below to troubleshoot operating problems.

Problem	Cause	Solution		
	Power cord connection is			
Power on, no response	not reliable	Improve connectivity		
	Fuse burning	Replace fuse		
	Warm up is not enough	Warm up more time		
	Glass cuvettes used in UV			
	Range	Use quartzcuvettes		
	Sample is not Stable	Improve the sample		
Measurement uncertainty	The concentration of	Diluted sample		
Measurement uncertainty	sample is too high	brideed bampie		
	Power Supply Voltage Low	Improve the Power Supply		
	or not Stable	TWPTOVE CHE POWET SUPPTY		
	Lamp damage or lamp life	Replace lamp		
	maturity	кертасе ташр		
Dark Current Error when	The lid of the			
self-check		Close the lid, restart		
SCII CHECK	during self-check			

System Calibrate Failed	Something	block	the	Remove	it,	calibrate
	Light path			again		
Power on, back light is						
OK, but nothing display	Dignlaw Cont	ragt proble	blom	Adjust	the	contrast
on the screen or display	Display Contrast proble		DIE	potentic	meter	
is not clear						
Measurements inaccurate	Cuvetteswere contaminated			Clean cuvettes		
	contaminated	1		25		
	Worse match	ing of	the	Improve	the ma	atching of
	cuvettes	uvettes the cuvettes				
	Dark current error		Resample dark current			

# Repair and Maintenance

### 1. Daily Maintain

#### Check the Compartment

After measurement, the cuvettes with sample solutions should be taken out of the compartment in time. Or the volatilization of the solution would make the mirror go moldy. Users must pay more attention to the corrosive sample and liquid easy to volatilize. Any solution remains in the compartment should be wiped off immediately.

#### Surface Clean

The cover of the instrument is with paint. Please use wet towel to wipe off the drips on the surface immediately. Organic solution is forbidden to be used to clean the cover. Please wipe off the dirt on the cover timely.

#### Clean the Cuvettes

After every test or after a solution change, the cuvettes should be cleaned carefully, or the remains on the surface would cause measuring error.

### 2. Spare Parts Replacement

#### Replace the Fuse



Danger! Be sure to switch off the power and unplug the socket before replacement!


Step 1. Tools preparation
 Prepare a 3×75 Flat Blade screwdriver.

Step 2. Switch Off the power supply

Switch off the power supply, and unplug the socket.


#### Step 3. Take out the Fuse Seat

Take out the fuse seat by the screwdriver.



#### Step 4. Replace a new fuse

Pick out the spare fuse (3.15A/250V) and replace it to the working position.



#### Step 5. Reset the fuse seat

Replace the fuse seat in the power socket.

#### Step 6. Switch on the power

Plug the socket and switch on the power.

#### Replace Lamps



Hot! Wait 20 minutes before open the lamp chamber after power off to avoid scald!

Step 1. Tools preparation
 Prepare a 6×150mm Cross Blade screwdriver and a pair of glove.

#### Step 2. Power Off


Switch off the power supply and unplug the socket.

#### Step 3. Open the cover

Unscrew the 4 screws indicated(Each side with 2 screws) and remove the cover.




# Step 4. Open the cover of the light chamber Unscrew the 2 screws on the light chamber cover and remove it.




#### Step 5. Replace the D2 lamp

Unscrew the 2 screws on the D2 Flange (No.1), unplug the connector in the Power Board (No. 2)and remove the D2 lamp. Draw on the cotton glove and replace a new lamp. Fix the 2 screws and plug the connector again.




#### Step 6. Replace W lamp

Pull out the defected W lamp and draw on the cotton glove. Insert the new W lamp as deep as possible on the lamp seat. Be sure to keep the filament in the same direction as the old one face.



Adjust the position of the W lamp

Switch on the power(the Switch Mirror should be placed to the position asindicates). Observe the entrance facular, and it should in the center of the entrance hole. If the facular deviate to Left or Right, then loosen the No.1 screws in Fig. 5-8 and move the lamp seat to Left or Right until it focus on the center of the slot. Then fix the screws. If the facular deviate to Up and Down, then loosen the No.2 screws and move the lamp seat Up and Down until the facular focus on the center of the slot. Then fix the No. 2 screws again.



#### Step 7. Finish

Reset the cover of the light chamber and fix the screws. Reset the cover of the instrument and fix the screws. Recover the Pole in the compartment, then the course finished.

#### Replace the Battery



Danger! Be sure to switch off the power and unplug the socket before replacement!

#### Step 1. Prepare the tools

Prepare a 6×150mm Cross Blade Screwdriver.

# Step 2. Switch off the power supply Switch off the power supply and unplug the socket.

### Step 3. Open the Bottom cover plate

Unscrew all the screws indicated then remove the bottom plate.



#### Step 4. Replace the Battery

Pick out the old battery and replace a new one.



#### Step 5. Finish

Recover the bottom plate and fix all the screws, then the course finishes.

### Warranty

We warrant that this product will be free from defects in material and workmanship for a period of one (1) year from date of purchase. If a defect is present, we will, at its option, repair, replace, or refund the purchase price of this product at no charge to you, provided it is returned during the warranty period. This warranty does not apply if the product has been damaged by accident, abuse, misuse, or misapplication, or from ordinary wear and tear.

For your protection, items being returned must be insured against possible damage or loss. This warranty shall be limited to the replacement of

defective products. IT IS EXPRESSLY AGREED THAT THIS WARRANTY WILL BE IN LIEU OF ALL WARRANTIES OF FITNESS AND IN LIEU OF THE WARRANTY OF MERCHANTABILITY.

### Equipment Disposal



This equipment is marked with the crossed out wheeled bin symbol to indicate that this equipment must not be disposed of with unsorted waste.

Instead it's your responsibility to correctly dispose of your equipment at lifecycle -end by handling it over to an authorized facility for separate collection and recycling. It's also your responsibility to decontaminate the equipment in case of biological, chemical and/or radiological contamination, so as to protect from health hazards the persons involved in the disposal and recycling of the equipment.

For more information about where you can drop off your waste of equipment, please contact your local dealer from whom you originally purchased this equipment.

By doing so, you will help to conserve natural and environmental resources and you will ensure that your equipment is recycled in a manner that protects human health.

Thank you!